



VIN

MECHANICAL EMISSIONS SERVICES LLC
7247 Otay Mesa Rd
San Diego, CA 92154
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5YFBURHE6GP433596		Year	2016	
Mfg In	UNITED STATES	Make	Toyota	Owner's Name	CP LOGISTICA S DE RL DE CV
Model	Corolla	License Plate	32 NONE	Odometer (mi)	115218 185424.93612 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET7-00003370	Geo Location	Latitude: 32.566967, Longitude: -116.920517	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	76 Juan M Wence	Inspector Signature	Juan M Wence	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20250813702596	Date	2025/08/15	Expires: 2025/11/15



Sernarat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

