



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	1G1ZE5ST8HF166085		Year	2017	
Mfg In	UNITED STATES	Make	Chevrolet	Owner's Name	CYNTHIA ARACELI VALENZUELA MARTINEZ
Model	Malibu	License Plate	N4 NONE	Odometer (mi)	183498 295310.67132 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET8-00003519	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	12 Christian Tovar	Inspector Signature	Christian Tovar
Catalyst Monitor	PASS	Overall Test Result	PASS	EEL ITN	X20250617166085	Date	2025/06/17 Expires: 2025/09/17



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

