



VIN

MECHANICAL EMISSIONS SERVICES LLC  
6225B Alameda Avenue  
El Paso, TX 79905  
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3N1CN7AP5JL812646		Year	2018	
Mfg In	MEXICO	Make	NISSAN	Owner's Name	ISABEL YAMILETH LOPEZ G
Model	Versa	License Plate	K2 NONE	Odometer (mi)	101247 162940.84698 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET8-00003522	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	12 Christian Tovar	Inspector Signature	Christian Tovar	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20250617812646	Date	2025/06/17	Expires: 2025/09/17



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

