



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	2T1BURHE7HC833961		Year	2017	
Mfg In	CANADA	Make	Toyota	Owner's Name	JOSE LUIS MEDINA CARRILLO
Model	Corolla	License Plate	K4 NONE	Odometer (mi)	108191 174116.10394 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET8-00008588	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	12 Christian Tovar	Inspector Signature	Christian Tovar
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20251020833961	Date	2025/10/20 Expires: 2026/01/20



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

