



VIN

MECHANICAL EMISSIONS SERVICES LLC  
6225B Alameda Avenue  
El Paso, TX 79905  
(619) 845-1299



Cert Number



Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	5NPD84LF7KH409507		Year	2019	
Mfg In	UNITED STATES	Make	Hyundai	Owner's Name	MIGUEL ANGEL LIRA GAYTAN
Model	Elantra	License Plate	K2 NONE	Odometer (mi)	105000 168980.70000 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET8-00008604	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	12 Christian Tovar	Inspector Signature	Christian Tovar	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20251020409507	Date	2025/10/20	Expires: 2026/01/20



Semarnat Authorization Letter  
No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 Software Version: 16028007727838  
To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

