



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3VW267AJXGM408419		Year	2016	
Mfg In	MEXICO	Make	Volkswagen	Owner's Name	MIGUEL ANGEL LIRA GAYTAN
Model	Jetta	License Plate	K4 NONE	Odometer (mi)	99587 160269.34258 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET8-00008606	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	12 Christian Tovar	Inspector Signature	Christian Tovar
Catalyst Monitor	PASS	Overall Test Result	PASS	EEL ITN	X20251020408419	Date	2025/10/20 Expires: 2026/01/20



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

