



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	2T1BURHE0JC022802		Year	2018	
Mfg In	CANADA	Make	Toyota	Owner's Name	NORMA GRACIELA ZAVALA CUEVAS
Model	Corolla	License Plate	A2 NONE	Odometer (mi)	77727 125089.17018 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET8-00011220	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	12 Christian Tovar	Inspector Signature	Christian Tovar	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20251208124887	Date	2025/12/10	Expires: 2026/03/10



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

