



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3CZRU5H70HM715650		Year	2017	
Mfg In	MEXICO	Make	Honda	Owner's Name	MONICA GONZALEZ CAZARES
Model	HR-V	License Plate	K2 NONE	Odometer (mi)	122152 196584.09968 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET8-00013336	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	12 Christian Tovar	Inspector Signature	Christian Tovar	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20260123715650	Date	2026/01/23	Expires: 2026/04/23



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

