



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3VWDB7AJ8HM218169		Year	2017	
Mfg In	MEXICO	Make	Volkswagen	Owner's Name	MAYTE BERENICE ALMARAZ MORALES
Model	Jetta	License Plate	K4 NONE	Odometer (mi)	130518 210047.83812 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET8-00013339	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	12 Christian Tovar	Inspector Signature	Christian Tovar
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20260123218169	Date	2026/01/23 Expires: 2026/04/23



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

